

Cycle	Route	Customer	Service Adc	Found Metc	Meter_Seriz	Found Rear	New Meter	New Transr	Pipe Type C	Pipe Type C	Status	Completor	Comments
15	103	ALRICK G B	137	ASHFO 5/8"	68311028	1878	13669918	1.57E+09	Copper	Galvanized	Completed	#####	
15	103	AMADOU T	135	SPRINC 5/8"	40336794	3221	13823339	1.57E+09	Copper	PVC	Completed	#####	
15	103	ANN R CRA	135	ASHFO 5/8"	90887996	766	13669917	1.57E+09	Copper	Galvanized	Completed	#####	
15	103	ARTIE ALLE	591	STONE 5/8"	84521831	1231	13669957	1.57E+09	Copper	PVC	Completed	#####	
15	103	BARBAREE	105	KENILV 5/8"	89386098	2628	13823295	1.57E+09	Copper	PVC	Completed	#####	_01-19-2023: Curb stop leaking
15	103	BARBRA J L	141	ASHFO 5/8"	84522468	4600	13669919	1.57E+09	Copper	Galvanized	Completed	#####	
15	103	BRANDI SC	128	ASHFO 5/8"	69166875	581	13823297	1.57E+09	Copper	PVC	Completed	#####	
15	103	CALANDRA	121	SPRINC 5/8"	84521704	2049	13823331	1.57E+09	Copper	PVC	Completed	#####	_01-19-2023: Customer flushed
15	103	CARL DWA	527	STONE 5/8"	76010225	4460	13669944	1.57E+09	Copper	PVC	Completed	#####	
15	103	CHAD DOM	209	MATLO 5/8"	84521854	1189	13669963	1.57E+09	Copper	Copper	Completed	#####	
15	103	CHAIPORN	106	MANDV 1"	48875426	30	12309109	1.57E+09	Copper	Galvanized	Completed	#####	
15	103	CHAIPORN	106	MANDV 5/8"	80926579	4199	13669880	1.57E+09	Copper	Galvanized	Completed	#####	
15	103	CHARLES J	118	ASHFO 5/8"	39937289	561	13669881	1.57E+09	Copper	Galvanized	Completed	#####	
15	103	CHRISTINE	107	ASHFO 5/8"	39937445	765	13669910	1.57E+09	Copper	Galvanized	Completed	#####	
15	103	CLAUDIA H	543	STONE 5/8"	78883258	2075	13669941	1.57E+09	Copper	PVC	Completed	#####	
15	103	COURTNEY	218	MATLO 5/8"	41310564	3035	13669967	1.57E+09	Copper	PVC	Completed	#####	
15	103	DAVID & H	5727	HUDC 5/8"	84521907	1099	13669923	1.57E+09	Copper	PVC	Completed	#####	
15	103	DAVID X CH	375	STONE 1"	87896405	1047	13669849	1.57E+09	Copper	PVC	Completed	#####	
15	103	DAWN R BL	5620	KEST 5/8"	35704404	1609	13669950	1.57E+09	Copper	PVC	Completed	#####	
15	103	DEWEY D V	495	STONE 5/8"	84521835	663	13669939	1.57E+09	Copper	PVC	Completed	#####	
15	103	DIANE PHIL	145	ASHFO 5/8"	36700754	363	13669920	1.57E+09	Copper	Galvanized	Completed	#####	_01-19-2023: Customer flush _01-19-2023: Customer flush meter wont tu _01-19-2023: Customer flush meter wont turn on
15	103	DON THOM	260	MATLO 5/8"	40356834	2279	13823285	1.57E+09	Copper	PVC	Completed	#####	_01-19-2023: Spigot weatherized unable to flush
15	103	DONALD L	134	ASHFO 5/8"	87896043	2708	13823298	1.57E+09	Copper	PVC	Completed	#####	
15	103	DONNA ML	103	KENILV 5/8"	36700759	1240	13823300	1.57E+09	Copper	PVC	Completed	#####	_01-19-2023: Greete home owner at door placed door tag in hand
15	103	DOROTHY	5712	HUDC 5/8"	84521905	2011	13669924	1.57E+09	Copper	PVC	Completed	#####	
15	103	DOROTHY	5642	TROW 5/8"	78320809	2810	13669945	1.57E+09	Copper	PVC	Completed	#####	
15	103	E DOYAL	226	MATLO 5/8"	94414562	517	13823288	1.57E+09	Copper	PVC	Completed	#####	_01-19-2023: Customer gave permission to use spigot
15	103	ERIN D. SH	5747	WAKE 5/8"	85756326	1588	13669955	1.57E+09	Copper	PVC	Completed	#####	
15	103	F RAY JACK	401	STONE 5/8"	82296963	585	13669852	1.57E+09	Copper	PVC	Completed	#####	_01-19-2023: Found off left off
15	103	FRANK E W	225	MATLO 5/8"	41310587	3276	13669968	1.57E+09	Copper	PVC	Completed	#####	_01-19-2023: Customer flushed line
15	103	GEO EDWA	104	HANOI 5/8"	84522322	1271	13823304	1.57E+09	Copper	PVC	Completed	#####	
15	103	GEORGE AI	5722	HUDC 5/8"	84521906	2380	13669933	1.57E+09	Copper	PVC	Completed	#####	
15	103	GEORGE S	126	ASHFO 5/8"	90361943	1180	13823302	1.57E+09	Copper	PVC	Completed	#####	
15	103	GLENN C V	103	MANDV 5/8"	80927306	2810	13669900	1.57E+09	Copper	Galvanized	Completed	#####	
15	103	IAN T KISTL	238	MATLO 5/8"	37912429	4844	13823287	1.57E+09	Copper	PVC	Completed	#####	_01-19-2023: Spigot weatherized unable to flush line
15	103	JACK L WOI	5823	HUDC 5/8"	84521803	1116	13669928	1.57E+09	Copper	PVC	Completed	#####	
15	103	JACK PYLE	127	ASHFO 5/8"	39937438	865	13669915	1.57E+09	Copper	PVC	Completed	#####	_01-19-2023: Spigot not av customer not home
15	103	JAMES BRE	5726	TROW 5/8"	84521772	2060	13823284	1.57E+09	Copper	PVC	Completed	#####	
15	103	JAMES HAT	125	ASHFO 5/8"	67446497	1158	13669916	1.57E+09	Copper	Galvanized	Completed	#####	
15	103	JAMES S SE	119	SPRINC 5/8"	39354428	4686	13823332	1.57E+09	Copper	Pex	Completed	#####	
15	103	JANET P FU	124	ASHFO 5/8"	76945911	2450	13823303	1.57E+09	Copper	PVC	Completed	#####	
15	103	JASON PEC	105	ASHFO 5/8"	90887779	1434	13669909	1.57E+09	Copper	Galvanized	Completed	#####	
15	103	JASON TIM	139	SPRINC 5/8"	38478267	3771	13823338	1.57E+09	Copper	PVC	Completed	#####	
15	103	JEANNA G F	110	SPRINC 5/8"	38882503	3982	13823326	1.57E+09	Copper	PVC	Completed	#####	_01-19-2023: Spigot winterized cannot flush
15	103	JEFFREY S I	120	ASHFO 5/8"	68311024	1670	13823301	1.57E+09	Copper	PVC	Completed	#####	
15	103	JENNIFER E	5715	TROW 5/8"	38534604	3466	13823307	1.57E+09	Copper	PVC	Completed	#####	_01-19-2023: Spigot weatherized unable to flush line
15	103	JENNIFER L	559	STONE 5/8"	84521832	2088	13669959	1.57E+09	Copper	PVC	Completed	#####	
15	103	JERROD D	5740	HUDC 5/8"	90888215	1058	13669938	1.57E+09	PVC	Copper	Completed	#####	
15	103	JIM BOYLES	5798	WAKE 5/8"	85756283	1449	13669927	1.57E+09	Copper	PVC	Completed	#####	
15	103	JOHN C RO	5715	HUDC 5/8"	46007781	2185	13669925	1.57E+09	Copper	PVC	Completed	#####	
15	103	JOHN DAVI	110	ASHFO 5/8"	84522518	1748	13669883	1.57E+09	Copper	Galvanized	Completed	#####	
15	103	JOHN LAUC	5921	HUDC 5/8"	69166869	430	13823312	1.57E+09	Copper	Copper	Completed	#####	_01-19-2023: Turned meter sideways to fit in pit
15	103	JOSEPH D E	5780	WAKE 5/8"	75447761	3320	13669930	1.57E+09	Copper	PVC	Completed	#####	
15	103	JOSEPH H J	5666	KEST 5/8"	35419395	2759	13669971	1.57E+09	Copper	PVC	Completed	#####	
15	103	JOSHUA TH	105	MANDV 5/8"	42687301	5722	13669879	1.57E+09	Copper	Galvanized	Completed	#####	
15	103	KAREN HAV	133	SPRINC 5/8"	42364443	2344	13823340	1.57E+09	Copper	PVC	Completed	#####	
15	103	KATHERINE	5857	HUDC 5/8"	84521808	1802	13823311	1.57E+09	Copper	Copper	Completed	#####	
15	103	KATHLEEN	123	ASHFO 5/8"	38478315	3897	13669914	1.57E+09	Copper	Galvanized	Completed	#####	

15	103 KENNETH F 5843 HUDC 5/8"	87897163	1673	13823310	1.57E+09	Copper	PVC	Completed	#####	
15	103 KENT MCC 132 ASHFO 5/8"	68310867	2148	13823299	1.57E+09	Copper	PVC	Completed	#####	
15	103 LARRY B ST 241 MATLO 5/8"	87897089	2675	13823291	1.57E+09	Copper	PVC	Completed	#####	_01-19-2023: Adjusted register head to fit pit
15	103 LEON DUM 5667 TROW 5/8"	78883260	1431	13669949	1.57E+09	Copper	PVC	Completed	#####	_01-19-2023: stomer flushed line _01-19-2023: Customer flushed line
15	103 LINDA L WI 5738 HUDC 5/8"	40357150	4797	13669935	1.57E+09	Copper	PVC	Completed	#####	
15	103 LINDY PEAC 425 STONE 5/8"	87897677	1078	13669942	1.57E+09	Copper	PVC	Completed	#####	
15	103 LUCILE M JI 5686 TROW 5/8"	41310584	2957	13669947	1.57E+09	Copper	PVC	Completed	#####	
15	103 MARC MILL 115 ASHFO 5/8"	80927113	1032	13669912	1.57E+09	Copper	Galvanized	Completed	#####	
15	103 MARSHALL 5741 HUDC 5/8"	84521909	1145	13669921	1.57E+09	Copper	PVC	Completed	#####	
15	103 MARY H HC 5604 KESTF 5/8"	84521928	1687	13823314	1.57E+09	Copper	PVC	Completed	#####	_01-19-2023: Spigot winterized cannot flush
15	103 MATT J MAF 115 SPRINC 5/8"	38535119	3379	13823333	1.57E+09	Copper	PVC	Completed	#####	_01-19-2023: Spigot winterized
15	103 MEAGAN N 113 ASHFO 5/8"	73451479	2606	13669913	1.57E+09	Copper	Galvanized	Completed	#####	_01-19-2023: Customer flush
15	103 MICHAEL E 5738 TROW 5/8"	90889226	1305	13823283	1.57E+09	Copper	PVC	Completed	#####	_01-19-2023: Spigot weatherized unable to flush line
15	98 MICHAEL K 255 TROTTI 5/8"	68858952	774	13823325	1.57E+09	Copper	PVC	Completed	#####	
15	103 MIHIR R PA 127 SPRINC 5/8"	44331577	4904	13823336	1.57E+09	Copper	PVC	Completed	#####	
15	103 MIKE NEISL 5619 TROW 5/8"	84521776	2014	13669960	1.57E+09	Copper	PVC	Completed	#####	
15	103 MOIRA A RE 5835 HUDC 5/8"	84521804	664	13823308	1.57E+09	Copper	PVC	Completed	#####	_01-19-2023: Adjusted register head to fit pit
15	103 MONTE CA' 5602 TROW 5/8"	84521777	2739	13669961	1.57E+09	Copper	PVC	Completed	#####	
15	103 NIYATEE K 116 ASHFO 5/8"	41162777	468	13669882	1.57E+09	Copper	Galvanized	Completed	#####	_01-19-2023: Spigot unav
15	103 NWABUEZI 116 SPRINC 5/8"	69167535	819	13823329	1.57E+09	Copper	Pex	Completed	#####	_01-19-2023: Cannot locate spigot
15	103 PATRICK TC 104 TRILLIL 5/8"	90887962	1415	13823293	1.57E+09	Copper	PVC	Completed	#####	_01-19-2023: Spigot weatherized couldnt flush line
15	103 PHI C. CHA 233 MATLO 5/8"	41310591	3770	13669966	1.57E+09	Copper	PVC	Completed	#####	
15	103 R & L PROP 5767 HUDC 5/8"	87895795	431	13669922	1.57E+09	Copper	PVC	Completed	#####	
15	103 RAYMOND 5701 HUDC 5/8"	38534414	2100	13669926	1.57E+09	Copper	PVC	Completed	#####	
15	103 RAYMOND 103 ASHFO 5/8"	84522520	1079	13669884	1.57E+09	Copper	Galvanized	Completed	#####	
15	103 REBECCA F 5635 TROW 5/8"	94413486	367	13669948	1.57E+09	Copper	PVC	Completed	#####	
15	103 REV KEVIN 143 ASHFO 5/8"	87099201	2767	13820983	1.57E+09	Copper	Galvanized	Completed	#####	
15	103 REX EVANS 511 STONE 5/8"	94413593	802	13669940	1.57E+09	Copper	PVC	Completed	#####	
15	103 RICKY GON 130 ASHFO 5/8"	84522514	922	13823296	1.57E+09	Copper	PVC	Completed	#####	
15	103 RITA G HAM 5764 WAKE 5/8"	85756282	375	13669932	1.57E+09	Copper	PVC	Completed	#####	_01-19-2023: Spoke with customer water is on
15	103 ROBERT DE 217 MATLO 5/8"	45496290	1720	13669965	1.57E+09	Copper	PVC	Completed	#####	
15	103 ROBERT L F 208 MATLO 5/8"	35419130	3908	13669965	1.57E+09	Copper	PVC	Completed	#####	
15	103 ROBERT M. 575 STONE 5/8"	84521833	1208	13669958	1.57E+09	Copper	PVC	Completed	#####	
15	103 ROHIT NATI 120 SPRINC 5/8"	89386025	1342	13823328	1.57E+09	Copper	PVC	Completed	#####	
15	99 RUSHELL B 101 GEORC 5/8"	44331430	1626	13823330	1.57E+09	Copper	PVC	Completed	#####	_01-19-2023: Spigot winterized cannot flush
15	103 SAM Z WU 129 SPRINC 5/8"	42214021	2515	13823334	1.57E+09	Copper	PVC	Completed	#####	
15	103 SAMUEL C. 5732 HUDC 5/8"	84521908	1215	13669934	1.57E+09	Copper	PVC	Completed	#####	
15	103 SHARON S 5620 TROW 5/8"	84521778	1088	13669962	1.57E+09	Copper	PVC	Completed	#####	
15	103 SHIJING DC 149 ASHFO 5/8"	78320455	1664	13820984	1.57E+09	Copper	Galvanized	Completed	#####	_01-19-2023: Customer flush
15	103 STACY L DA 5773 HUDC 5/8"	68259030	631	13669929	1.57E+09	Copper	PVC	Completed	#####	
15	103 STEPHANIE 134 SPRINC 5/8"	40337100	3247	13823337	1.57E+09	Copper	PVC	Completed	#####	_01-19-2023: Door banner to customer
15	103 STEVEN J P. 114 ASHFO 5/8"	39937444	867	13669911	1.57E+09	Copper	Galvanized	Completed	#####	
15	103 SUE W BRY 259 MATLO 5/8"	90362085	2383	13669974	1.57E+09	Copper	PVC	Completed	#####	_01-19-2023: Found off left off
15	103 SUMMER TI 5756 WAKE 5/8"	85756281	1976	13669954	1.57E+09	Copper	PVC	Completed	#####	
15	103 SUSANA RC 5625 KESTF 5/8"	84521887	1448	13823315	1.57E+09	Copper	PVC	Completed	#####	
15	103 SUZANNE F 475 STONE 5/8"	84521784	1516	13669943	1.57E+09	Copper	PVC	Completed	#####	
15	103 TAMMY JOH 124 SPRINC 5/8"	38534938	3010	13823327	1.57E+09	Copper	PVC	Completed	#####	_01-19-2023: Spigot winterized cannot flush
15	103 TERRY CAS 5770 WAKE 5/8"	40781869	5080	13669931	1.57E+09	Copper	PVC	Completed	#####	
15	103 TERRY D BF 5895 HUDC 5/8"	84521780	1501	13823309	1.57E+09	Copper	PVC	Completed	#####	
15	103 TERRY W BI 5735 TROW 5/8"	84521774	1518	13823286	1.57E+09	Copper	PVC	Completed	#####	_01-19-2023: Got permission from customer to use spigot
15	103 THOMAS E 5653 KESTF 5/8"	84521886	1128	13823313	1.57E+09	Copper	PVC	Completed	#####	_01-19-2023: Spigot winterized
15	103 THOMAS H 125 SPRINC 5/8"	39754371	4173	13823335	1.57E+09	Copper	Pex	Completed	#####	
15	103 TRACEY LYI 130 SPRINC 5/8"	39754521	4311	13823341	1.57E+09	Copper	PVC	Completed	#####	_01-19-2023: Cannot locate spigot
15	103 TROY D MIL 106 TRILLIL 5/8"	40356584	5521	13823294	1.57E+09	Copper	PVC	Completed	#####	_01-19-2023: Customer flushed line
15	103 ULYSSES B 5675 KESTF 5/8"	84521882	1784	13823318	1.57E+09	Copper	PVC	Completed	#####	_01-19-2023: Spigot winterized
15	103 VIRGINIA O 122 ASHFO 5/8"	40337150	1856	13823306	1.57E+09	Copper	PVC	Completed	#####	
15	103 VISHAL PAI 103 HANOI 5/8"	84522321	1333	13823305	1.57E+09	Copper	Pex	Completed	#####	
15	103 W R BAKEF 5668 TROW 5/8"	41310585	4136	13669946	1.57E+09	Copper	PVC	Completed	#####	_01-19-2023: Customer flushed line
15	103 ZACHARY C 128 SPRINC 5/8"	38882538	4810	13823342	1.57E+09	Copper	PVC	Completed	#####	