



OVERFLOW REPORT

BOARD MEMBERS

Gary Bechtel
Chairman

Frank Patterson
Vice-Chairman

Elaine H. Lucas

Marshall Talley

Dwight Jones

Bill Howell

Valerie Wynn

Michel Wanna
Executive Director
& President

790 Second Street
P.O.Box 108
Macon, GA 31202
(478) 464-5600
Fax: (478) 750-2007
MaconWater.org

DATE OF OVERFLOW: Wednesday, October 7, 2026, 10:15 am – 10:20 am

REPORT SUBMITTED: Monday, October 12, 2026

LOCATION OF OVERFLOW: [111 Harbor Drive](#) – Force Main ID: 18
(Please note that the address used is a reference for the location of the force main.)

CAUSE OF OVERFLOW: This minor overflow was caused by a contractor's ruptured bypass hose.

ESTIMATED VOLUME DISCHARGED: 400 gallons
(Please note that this quantity is only a calculated **estimation** of the volume of sewage that spilled from our system. More sewage may have escaped the system.)

SERVICE BASIN AFFECTED: Tobesofkee

CORRECTIVE ACTION TAKEN TO MITIGATE OR TO REDUCE ADVERSE EFFECTS: Debris has been removed. This area has also been sprayed with an enzyme treatment for organic waste called Bio-bug.

OVERFLOW STATUS: Sewage is no longer escaping.

SIGNS POSTED: Wednesday, October 7, 2026

CORRECTIVE ACTION TAKEN TO PREVENT FUTURE OVERFLOW: The bypass hose has been replaced.

MEDIA / HEALTH DEPARTMENT / OTHERS NOTIFIED: Monroe County / Macon Reporter and Macon-Bibb County Health Department

REPORT SUBMITTED BY: Marlayzha Griffin