Macon Water Authority

BOARD MEMBERS
Gary Bechtel
Chairman
Frank Patterson
Vice-Chairman
Elaine H. Lucas
Marshall Talley
Dwight Jones
Bill Howell
Valerie Wynn

Michel Wanna
Executive Director
& President

790 Second Street
P.O.Box 108
Macon, GA 31202
(478) 464-5600
Fax: (478) 750-2007
MaconWater.org

OVERFLOW REPORT

DATE OF OVERFLOW: Tuesday, November 3, 2026, 11:50 am – 4:20 pm

REPORT SUBMITTED: Friday, November 6, 2026

LOCATION OF OVERFLOW: 2440 Broadway – MH ID: 60882
(Please note that the address used is a reference for the location of the manhole.)

CAUSE OF OVERFLOW: After clearing the blockage, we determined that the minor overflow was caused by grease and roots in the sewer main. A commercial source of grease has been identified upstream from this location.

ESTIMATED VOLUME DISCHARGED: 6,375 gallons
*(Please note that this quantity is only a calculated **estimation** of the volume of sewage that spilled from our system. More sewage may have escaped the system.)*

SERVICE BASIN AFFECTED: Bay Street

CORRECTIVE ACTION TAKEN TO MITIGATE OR TO REDUCE ADVERSE EFFECTS: The blockage has been cleared, and debris has been removed. This area has also been sprayed with an enzyme treatment for organic waste called Bio-bug.

OVERFLOW STATUS: Sewage is no longer escaping.

SIGNS POSTED: Tuesday, November 3, 2026

CORRECTIVE ACTION TAKEN TO PREVENT FUTURE OVERFLOW: This line is scheduled for cleaning and CCTV inspection. It will also be added to the Hotspot Inspection list for ongoing monitoring and is expected to be chemically treated for root intrusion. Additionally, the details of this overflow have been forwarded to our Grease Management team for further investigation. This line has been recommended for CIPP rehabilitation.

MEDIA / HEALTH DEPARTMENT / OTHERS NOTIFIED: Monroe County / Macon Reporter and Macon-Bibb County Health Department

REPORT SUBMITTED BY: Marlayzha Griffin