

R.A. "Tony" Rojas Executive Director & President

Macon Water Authority

790 Second Street * P.O. Box 108 Macon, GA 31202-0108 (478) 464-5600 * FAX (478) 750-2007 Visit Us @ www.maconwater.org

Members

Samuel F. Hart, Sr., Chairman Frank Patterson, Vice-Chairman Javors J. Lucas Dorothy "Dot" C. Black Dwight Jones Bert Bivins, III Gary Bechtel

OVERFLOW REPORT

DATE OF OVERFLOW: Saturday, February 18, 2017 12:00pm - 4:00pm

REPORT SUBMITTED: Monday, February 20, 2017

LOCATION OF OVERFLOW: 3266 Hillcrest Avenue, MH ID 61907

(Please note that the address used is a reference for the location of the manhole.)

CAUSE OF OVERFLOW: After the blockage was removed, it was determined that the cause of this overflow was grease. There are no commercial sources of grease upstream from this location and residential grease is not regulated.

ESTIMATED VOLUME DISCHARGED: 720 gallons

(Please note that this quantity is only a calculated **estimation** of the volume of sewage that spilled from our system. More sewage may have escaped the system.)

SERVICE BASIN AFFECTED: Lower Rocky Creek

CORRECTIVE ACTION TAKEN TO MITIGATE OR TO REDUCE ADVERSE EFFECTS: Debris has been removed from the area and the sewage was washed back into the manhole.

OVERFLOW STATUS: The blockage has been removed; sewage is no longer escaping.

SIGNS POSTED: Monday, February 20, 2017

CORRECTIVE ACTION TAKEN TO PREVENT FUTURE OVERFLOW: This line is scheduled to be cleaned with grease emulsifier and televised. It will also be added to the weekly Hot Spot Inspection list.

MEDIA / HEALTH DEPARTMENT / OTHERS NOTIFIED: Macon Telegraph and Macon – Bibb County Health Department