

OVERFLOW REPORT

BOARD MEMBERS Gary Bechtel

Chairman Frank Patterson Vice-Chairman Elaine H. Lucas **Desmond Brown**

LOCATION OF OVERFLOW: North Ohara Lift Station - Lift Station ID: 58

DATE OF OVERFLOW: Tuesday, April 8, 2025, 8:25 am – 8:37 am

Dwight Jones Bill Howell

Valerie Wynn

CAUSE OF OVERFLOW: The cause of this minor overflow was a bypass pump malfunction.

Ron Shipman Executive Director & President

ESTIMATED VOLUME DISCHARGED: 300 gallons

REPORT SUBMITTED: Friday, April 11, 2025

(Please note that this quantity is only a calculated estimation of the volume of sewage

that spilled from our system. More sewage may have escaped the system.)

SERVICE BASIN AFFECTED: O'Hara

790 Second Street

CORRECTIVE ACTION TAKEN TO MITIGATE OR TO REDUCE ADVERSE EFFECTS:

This area has also been sprayed with an enzyme treatment for organic waste called Bio-

bug.

P.O.Box 108 Macon, GA 31202 (478) 464-5600 Fax: (478) 750-2007

OVERFLOW STATUS: Sewage is no longer escaping.

SIGNS POSTED: Wednesday, April 9, 2025

MaconWater.org

CORRECTIVE ACTION TAKEN TO PREVENT FUTURE OVERFLOW: The pump has

been repaired, and the lift station is being monitored.

MEDIA / HEALTH DEPARTMENT / OTHERS NOTIFIED: Macon Telegraph and Macon-

Bibb County Health Department

REPORT SUBMITTED BY: Marlayzha Griffin