

OVERFLOW REPORT

BOARD MEMBERS	DATE OF OVERFLOW: Friday, May 23, 2025, 7:10 pm – 10:15 pm
Gary Bechtel Chairman	REPORT SUBMITTED: Wednesday, May 28, 2025
Frank Patterson <i>Vice-Chairman</i> Elaine H. Lucas	LOCATION OF OVERFLOW: <u>5345 Nisbet Drive</u> – MH ID: 55229 (Please note that the address used is a reference for the location of the manhole.)
Desmond Brown Dwight Jones Bill Howell Valerie Wynn	CAUSE OF OVERFLOW: After clearing the blockage, we determined that the minor overflow was caused by grease in the sewer main. No commercial sources of grease have been identified upstream from this location.
Ron Shipman Executive Director & President	ESTIMATED VOLUME DISCHARGED: 2,775 gallons (Please note that this quantity is only a calculated estimation of the volume of sewage that spilled from our system. More sewage may have escaped the system.)
	SERVICE BASIN AFFECTED: Lower Rocky Creek
790 Second Street	CORRECTIVE ACTION TAKEN TO MITIGATE OR TO REDUCE ADVERSE EFFECTS:
P.0.Box 108 Macon, GA 31202	The blockage has been cleared, and debris has been removed. This area has also been sprayed with an enzyme treatment for organic waste called Bio-bug.
(478) 464-5600 Fax: (478) 750-2007	OVERFLOW STATUS: The blockage has been removed; sewage is no longer escaping.
MaconWater.org	SIGNS POSTED: Friday, May 23, 2025
	CORRECTIVE ACTION TAKEN TO RREVENT FUTURE OVERELOW. This line is

CORRECTIVE ACTION TAKEN TO PREVENT FUTURE OVERFLOW: This line is scheduled for cleaning and CCTV inspection. It will also be added to the Hotspot Inspection list for ongoing monitoring. Additionally, the details of this overflow have been forwarded to our Grease Management team for further investigation. We will continue to monitor this location

MEDIA / HEALTH DEPARTMENT / OTHERS NOTIFIED: Macon Telegraph and Macon-Bibb County Health Department

REPORT SUBMITTED BY: Marlayzha Griffin