



OVERFLOW REPORT

BOARD MEMBERS

Gary Bechtel

Chairman

Frank Patterson

Vice-Chairman

Elaine H. Lucas

Desmond Brown

Dwight Jones

Bill Howell

Valerie Wynn

Ron Shipman

Executive Director

& President

790 Second Street

P.O.Box 108

Macon, GA 31202

(478) 464-5600

Fax: (478) 750-2007

MaconWater.org

DATE OF OVERFLOW: Friday, October 10, 2025, 12:15 pm – 12:30 pm

REPORT SUBMITTED: Monday, October 13, 2025

LOCATION OF OVERFLOW: [4685 Presidential Pkwy](#) – Line ID: 20713
(Please note that the address used is a reference for the location of the gravity main.)

CAUSE OF OVERFLOW: We determined that the minor overflow was caused by a pump malfunction due to a deflated plug for a temporary sewer bypass.

ESTIMATED VOLUME DISCHARGED: 500 gallons
(Please note that this quantity is only a calculated **estimation** of the volume of sewage that spilled from our system. More sewage may have escaped the system.)

SERVICE BASIN AFFECTED: Lower Rocky Creek

CORRECTIVE ACTION TAKEN TO MITIGATE OR TO REDUCE ADVERSE EFFECTS: Debris has been removed from the area. The affected area has also been treated with an enzyme-based organic waste treatment called Bio-bug.

OVERFLOW STATUS: Sewage is no longer escaping.

SIGNS POSTED: Friday, October 10, 2025

CORRECTIVE ACTION TAKEN TO PREVENT FUTURE OVERFLOW: The issue with the plug has been resolved, and power for the pump has been restored. The contractor will continue to monitor the temporary bypass.

MEDIA / HEALTH DEPARTMENT / OTHERS NOTIFIED: Macon Telegraph and Macon-Bibb County Health Department

REPORT SUBMITTED BY: Marlayzha Griffin