



R.A. "Tony" Rojas
Executive Director & President

Macon Water Authority

790 Second Street * P.O. Box 108
Macon, GA 31202-0108
(478) 464-5600 * FAX (478) 750-2007
Visit Us @ www.maconwater.org

Members

Samuel F. Hart, Sr., Chairman
Frank Patterson, Vice-Chairman
Javors J. Lucas
Dorothy "Dot" C. Black
Dwight Jones
Bert Bivins, III
Larry Schlesinger

OVERFLOW REPORT

DATE OF OVERFLOW: Thursday, October 11, 2018 1:20am – 8:10am

REPORT SUBMITTED: Monday, October 15, 2018

LOCATION OF OVERFLOW: [975 South Confederate Drive, South Confederate Lift Station](#)
(Please note that the address used is a reference for the location of the lift station.)

CAUSE OF OVERFLOW: The cause of this minor overflow was a lift station failure.

ESTIMATED VOLUME DISCHARGED: 4680 gallons
*(Please note that this quantity is only a calculated **estimation** of the volume of sewage that spilled from our system. More sewage may have escaped the system.)*

SERVICE BASIN AFFECTED: Upper Rocky Creek

CORRECTIVE ACTION TAKEN TO MITIGATE OR TO REDUCE ADVERSE EFFECTS: Debris has been removed from the area and the affected area has been disinfected with lime.

OVERFLOW STATUS: Sewage is no longer escaping.

SIGNS POSTED: October 11, 2018

CORRECTIVE ACTION TAKEN TO PREVENT FUTURE OVERFLOW: Power was returned to the station and the station returned to normal operations.

MEDIA / HEALTH DEPARTMENT / OTHERS NOTIFIED: Macon Telegraph and Macon – Bibb County Health Department