

R.A. "Tony" Rojas Executive Director & President

Macon Water Authority

790 Second Street * P.O. Box 108 Macon, GA 31202-0108 (478) 464-5600 * FAX (478) 750-2007 Visit Us @ www.maconwater.org

Members

Samuel F. Hart, Sr., Chairman Frank Patterson, Vice-Chairman Javors J. Lucas Dorothy "Dot" C. Black Dwight Jones Bert Bivins, III Ed DeFore

OVERFLOW REPORT

DATE OF OVERFLOW: Monday, January 2, 2017 6:30am - 11:34am

REPORT SUBMITTED: Friday, January 6, 2017

LOCATION OF OVERFLOW: 3279 Ohara Drive North, North Ohara Lift Station, MH ID 52091

(Please note that the address used is a reference for the location of the manhole.)

CAUSE OF OVERFLOW: The cause of this overflow was hydraulic overload due to heavy rains in the MWA service area and a failure of the by-pass pump at the lift station.

ESTIMATED VOLUME DISCHARGED: 4,985 gallons

(Please note that this quantity is only a calculated **estimation** of the volume of sewage that spilled from our system. More sewage may have escaped the system.)

SERVICE BASIN AFFECTED: Ohara

CORRECTIVE ACTION TAKEN TO MITIGATE OR TO REDUCE ADVERSE EFFECTS: Debris has been removed from the area and the affected area has been disinfected with lime.

OVERFLOW STATUS: The pump was repaired; sewage stopped escaping.

SIGNS POSTED: Monday, January 2, 2017

CORRECTIVE ACTION TAKEN TO PREVENT FUTURE OVERFLOW: The pump issue was corrected and service was restored to the station.

MEDIA / HEALTH DEPARTMENT / OTHERS NOTIFIED: Macon Telegraph and Macon – Bibb County Health Department