

R.A. "Tony" Rojas Executive Director & President

790 Second Street * P.O. Box 108 Macon, GA 31202-0108 (478) 464-5600 * FAX (478) 750-2007 Visit Us @ www.maconwater.org

Members

Samuel F. Hart, Sr., Chairman Frank Patterson, Vice-Chairman Javors J. Lucas Dorothy "Dot" C. Black Dwight Jones Bert Bivins, III Gary Bechtel

MINOR SPILL REPORT TO EPD

DATE OF MINOR SPILL: Saturday, January 21, 2017 10:35am – 1:30pm

REPORT SUBMITTED: Monday, January 23, 2017

LOCATION OF MINOR SPILL: 103 Country Oaks Drive, MH ID 62635

(Please note that the address used is a reference for the location of the manhole.)

CAUSE OF MINOR SPILL: After the blockage was removed, it was determined that the cause of this minor spill was grease and roots. There are no commercial sources of grease upstream from this location and residential grease is not regulated.

ESTIMATED VOLUME DISCHARGED: 1,400 gallons

(Please note that this quantity is only a calculated estimation of the volume of sewage that spilled from our system. More sewage may have escaped the system.)

RECEIVING WATERS: Ditch feeding Rocky Creek

SERVICE BASIN AFFECTED: Upper Rocky Creek

CORRECTIVE ACTION TAKEN TO MITIGATE OR TO REDUCE ADVERSE EFFECTS: Debris has been removed from the area and the affected area is being disinfected with lime.

SPILL STATUS: The blockage was removed; sewage is no longer escaping.

SIGNS POSTED: Saturday, January 21, 2017

CORRECTIVE ACTION TAKEN TO PREVENT FUTURE SPILL: This line is scheduled to be cleaned with grease emulsifier and televised. It will also be chemically treated for root control.

MEDIA / HEALTH DEPARTMENT / OTHERS NOTIFIED: Macon Telegraph, WMAZ (TV), WMGT (Radio), Macon – Bibb County Health Department, State of Georgia Health Department,