

OVERFLOW REPORT

BOARD MEMBERS
Gary Bechtel
Chairman
Frank Patterson
Vice-Chairman
Calder B. Clay III
Desmond Brown

Valerie Wynn

Ron Shipman

Executive Director

Dwight Jones

Bill Howell

& President

790 Second Street

P.O.Box 108 Macon, GA 31202 (478) 464-5600 Fax: (478) 750-2007 **MaconWater.org** DATE OF OVERFLOW: Wednesday, July 3, 2024, 9:47 am - 11:20 am

REPORT SUBMITTED: Friday, July 5, 2024

LOCATION OF OVERFLOW: Behind 239 Ridgewood Avenue – MH ID: 70898 (Please note that the address used is a reference for the location of the manhole.)

CAUSE OF OVERFLOW: After the blockage was removed, it was determined that the causes of this minor overflow were grease and rags. There is a commercial source of grease upstream from the location.

ESTIMATED VOLUME DISCHARGED: 1,740 gallons

(Please note that this quantity is only a calculated **estimation** of the volume of sewage that spilled from our system. More sewage may have escaped the system.)

SERVICE BASIN AFFECTED: Corbin Avenue

CORRECTIVE ACTION TAKEN TO MITIGATE OR TO REDUCE ADVERSE EFFECTS:

The blockage has been cleared and debris has been removed. This area has also been sprayed with an enzyme treatment for organic waste called Bio-bug.

OVERFLOW STATUS: Sewage is no longer escaping.

SIGNS POSTED: July 3, 2024

CORRECTIVE ACTION TAKEN TO PREVENT FUTURE OVERFLOW: The details of this overflow have been forwarded to our Grease Management team for further investigation. This line is scheduled to be cleaned with grease emulsifier and televised. It has also been added to the Hotspot Inspection list for monitoring.

MEDIA / HEALTH DEPARTMENT / OTHERS NOTIFIED: Macon Telegraph and Macon-Bibb County Health Department

REPORT SUBMITTED BY: Bryan Jones