

OVERFLOW REPORT

BOARD MEMBERS
Gary Bechtel
Chairman
Frank Patterson
Vice-Chairman
Elaine H. Lucas
Desmond Brown
Dwight Jones
Bill Howell
Valerie Wynn

Ron Shipman Executive Director & President

790 Second Street

DATE OF OVERFLOW: Thursday, January 2, 2025, 4:51 pm – 6:30 pm

REPORT SUBMITTED: Friday, January 3, 2025

LOCATION OF OVERFLOW: <u>1495 Briarcliff Road</u> – MH ID: 65997 (Please note that the address used is a reference for the location of the manhole.)

CAUSE OF OVERFLOW: After removing the blockage, we determined that the minor overflow was caused by roots in the sewer main.

ESTIMATED VOLUME DISCHARGED: 810 gallons (Please note that this quantity is only a calculated **estimation** of the volume of sewage that spilled from our system. More sewage may have escaped the system.)

SERVICE BASIN AFFECTED: Main Street

CORRECTIVE ACTION TAKEN TO MITIGATE OR TO REDUCE ADVERSE EFFECTS: The blockage has been cleared and debris has been removed. This area has also been sprayed with an enzyme treatment for organic waste called Bio-bug.

P.0.Box 108 Macon, GA 31202 (478) 464-5600 Fax: (478) 750-2007 MaconWater.org

OVERFLOW STATUS: Sewage is no longer escaping.

SIGNS POSTED: Friday, January 3, 2025

CORRECTIVE ACTION TAKEN TO PREVENT FUTURE OVERFLOW: This line is scheduled for cleaning and CCTV inspection. It will also be added to the Hotspot Inspection list for ongoing monitoring. Additionally, the line is expected to undergo chemical treatment for root intrusion.

MEDIA / HEALTH DEPARTMENT / OTHERS NOTIFIED: Macon Telegraph and Macon-Bibb County Health Department

REPORT SUBMITTED BY: Bryan Jones