



## OVERFLOW REPORT

### BOARD MEMBERS

Gary Bechtel

Chairman

Frank Patterson

Vice-Chairman

Elaine H. Lucas

Desmond Brown

Dwight Jones

Bill Howell

Valerie Wynn

Ron Shipman

Executive Director  
& President

790 Second Street

P.O.Box 108

Macon, GA 31202

(478) 464-5600

Fax: (478) 750-2007

[MaconWater.org](http://MaconWater.org)

**DATE OF OVERFLOW:** Friday, May 30, 2025, 2:55 pm – 4:45 pm

**REPORT SUBMITTED:** Monday, June 2, 2025

**LOCATION OF OVERFLOW:** [2933 Leone Drive North](#) – MH ID: 52038  
(Please note that the address used is a reference for the location of the manhole.)

**CAUSE OF OVERFLOW:** After clearing the blockage, we determined that the minor overflow was caused by grease in the sewer main. No commercial sources of grease have been identified upstream from this location.

**ESTIMATED VOLUME DISCHARGED:** 2,200 gallons  
(Please note that this quantity is only a calculated **estimation** of the volume of sewage that spilled from our system. More sewage may have escaped the system.)

**SERVICE BASIN AFFECTED:** Lower Rocky Creek

**CORRECTIVE ACTION TAKEN TO MITIGATE OR TO REDUCE ADVERSE EFFECTS:**  
The blockage has been cleared and debris has been removed. This area has also been sprayed with an enzyme treatment for organic waste called Bio-bug.

**OVERFLOW STATUS:** The blockage has been removed; sewage is no longer escaping.

**SIGNS POSTED:** Friday, May 30, 2025

**CORRECTIVE ACTION TAKEN TO PREVENT FUTURE OVERFLOW:** This line is scheduled for cleaning and CCTV inspection. It will also be added to the Hotspot Inspection list for ongoing monitoring. Additionally, the details of this overflow have been forwarded to our Grease Management team for further investigation.

**MEDIA / HEALTH DEPARTMENT / OTHERS NOTIFIED:** Macon Telegraph and Macon-Bibb County Health Department

**REPORT SUBMITTED BY:** Marlayzha Griffin