



MACON WATER AUTHORITY

790 Second Street * P.O. Box 108
Macon, GA 31202-0108
(478) 464-5600 * FAX (478) 750-2007
Visit Us @ www.maconwater.org

R.A. "Tony" Rojas
Executive Director & President

Members:

Samuel F. Hart, Sr., Chairman
Frank Patterson, Vice-Chairman
Bert Bivins, III
Dr. Anissa Jones
Dwight Jones
Javors J. Lucas
Larry Schlesinger

MAJOR SPILL REPORT TO EPD

EPD Watershed Protection Branch

DATE OF MAJOR SPILL: Friday, January 4, 2019 12:21pm – 7:00pm

REPORT SUBMITTED: Monday, January 7, 2019

LOCATION OF MAJOR SPILL: [Intersection of Brookdale Ave and Melrose St](#), MH ID 60927
(Please note that the address used is a reference for the location of the manhole.)

CAUSE OF MAJOR SPILL: The cause of this major spill was hydraulic overload due to heavy rains in the MWA service area.

ESTIMATED VOLUME DISCHARGED: 12,740 gallons
(Please note that this quantity is only a calculated estimation of the volume of sewage that spilled from our system. More sewage may have escaped the system.)

RECEIVING WATERS: Tributary to Rocky Creek

SERVICE BASIN AFFECTED: Lower Rocky Creek

WRF SERVICE AREA NPDES PERMIT: Rocky Creek WRF Permit: GA0024546

CORRECTIVE ACTION TAKEN TO MITIGATE OR TO REDUCE ADVERSE EFFECTS: Debris will be removed from the area and the affected area disinfected with lime.

SPILL STATUS: Sewage is no longer escaping.

SIGNS POSTED: Monday, January 7, 2019

CORRECTIVE ACTION TAKEN TO PREVENT FUTURE SPILL: The Macon Water Authority will continue its investigation for sources of inflow and infiltration into its system.

MONITORING INITIATED: Monitoring of upstream and downstream sites began on Monday, January 7, 2019.

MEDIA / HEALTH DEPARTMENT / OTHERS NOTIFIED: Macon Telegraph, WMAZ (TV), WMGT (Radio), WGXA, Macon – Bibb County Health Department, State of Georgia Health Department